Certificate Number E241484

Report Reference E241484-20040127

Date 2022-October-28

Issued to: Radix Wire and Cable, LLC

30333 Emerald Valley Pkwy

Glenwillow OH, 44139-4394 United States

This is to certify that representative samples of

POWER-LIMITED FIRE ALARM CABLE

Type FPL, FPLR (60 °C to 90 °C).

Have been evaluated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1424, Cables for Power-Limited Fire-Alarm Circuits.

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.





Certificate Number E241484

Report Reference E241484-20200224

Date 2022-October-28

Radix Wire and Cable, LLC Issued to:

30333 Emerald Valley Pkwy

Glenwillow OH, 44139-4394 United States

This is to certify that representative samples of POWER-LIMITED FIRE ALARM CABLE

Type FPLP (60 °C - 200 °C).

Have been evaluated by UL in accordance with the

Standard(s) indicated on this Certificate.

UL 1424, Cables for Power-Limited Fire-Alarm Circuits. Standard(s) for Safety:

Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.











Certificate Number E241484

Report Reference E241484-20170616

Date 2022-October-28

Radix Wire and Cable, LLC Issued to:

30333 Emerald Valley Pkwy

Glenwillow OH, 44139-4394 United States

This is to certify that representative samples of POWER-LIMITED FIRE ALARM CABLE

Type FPLP-CI (60 °C, 75 °C).

Have been evaluated by UL in accordance with the

Standard(s) indicated on this Certificate.

UL 1424, Cables for Power-Limited Fire-Alarm Circuits. Standard(s) for Safety:


Additional Information: See the UL Online Certifications Directory at

https://iq.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.









Certificate Number E241484

Report Reference E241484-20180406

Date 2022-October-28

Issued to: Radix Wire and Cable, LLC

30333 Emerald Valley Pkwy

Glenwillow OH, 44139-4394 United States

This is to certify that POWER-LIM representative samples of

POWER-LIMITED FIRE ALARM CABLE Type FPL-CI, FPLR-CI (60 °C to 90 °C).

Have been evaluated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1424, Cables for Power-Limited Fire-Alarm Circuits.

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.



